

# Mill Brook Stream Bank Stabilization and Habitat Enhancement Project September 2007








**Left - Root wad and native tree stacking.**


**Below - Anchoring of root wads to boulders and or live native trees**



**Cable anchoring root wad to live native tree**



**Eye bolt and cable for anchoring**







Rock vein with  
root wads  
packed around  
and behind.

Boulder placement to  
encourage pool formation and  
slow velocity.



Temporary dam re-  
moved and feathering of  
stream bed





**Before**



**After**









**Seeding and Hay bare areas with winter rye**







**Boom for protection against possible oil/fuel leaks from equipment**



**Access/entrance area blocked by boulders and six white pines.**

**Access road also stabilized with brush, winter rye and hay.**