

**Mill Brook
Westbrook**

**Preliminary Culvert Photos
2003 & 2007**



Rte 302



Shallow water (at certain times of year)
and flat, concrete bottom.




Alewives below a debris jam
near Rte 302 -- 5/31/03


Rte 302



12/11/07







Austin St

Apparent, engineered log "dam" placed at upstream End of right culvert. Appears To be there to encourage fish to use other culvert.

This is a good idea. Still, the left culvert bottom is flat concrete and may still prove to be somewhat of a fish barrier.



Unimpeded culvert opening ?
Couldn't tell for sure?

12/11/07

E. Bridge St.



alewives

Photographs of the culverts underneath Bridge Street: A) taken on May 20, 2003; and B-C) taken on July 14, 2003.

